Yonkers Public Schools - Potable Water Outlets Sampling, Test Results and Action

Method of Analysis FPA Method 200.8 Rev. 5.4

	Method of Analysis EPA Method 200.8 F						S EPA Method 200.8 Rev. 5.
BOE ID#	Lab ID#	Date of Collection	Sample Description	Initial / Flushed	Lead Concentration ug/L (LT 1.0 = Less Than 1.0)	Date of Analysis	ACTION TAKEN
001	16-3267	4-1-16	Rm 115 Sink #1 by wall	Initial	10.9	4-3-16	
003	16-3269	4-1-16	Rm 115 Sink #2	Initial	5.32	4-3-16	
005	16-3271	4-1-16	Rm 115 Sink #3	Initial	5.6	4-3-16	
007	16-3273	4-1-16	BUILDING SERVICE SPIGOT	Initial	LT 1.00	4-3-16	
009	16-3275	4-1-16	1st Floor Rm 107 Bubbler - Chiller	Initial	LT 1.00	4-3-16	
010	16-3276	4-1-16	2nd Floor Rm 211 Bubbler - Chiller	Initial	LT 1.00	4-3-16	
011	7090616001	5-18-19	2nd Fl Hall by Rm 204 Sink #1	Initial	1.4	5-29-19	RETURN TO USE
012	16-3278	4-1-16	"	Flushed	4.67	4-4-16	
013	16-3279	4-1-16	2nd Fl Hall by Rm 204 Sink #2	Initial	8.42	4-3-16	
015	16-3281	4-1-16	2nd Fl Hall by Rm 210 Sink #1	Initial	4.43	4-3-16	
017	7090616002	5-18-19	2nd Fl Hall by Rm 210 Sink #2	Initial	1.2	5-29-19	RETURN TO USE
018	16-3284	4-1-16	"	Flushed	2.52	4-4-16	
021	16-3287	4-1-16	2nd Fl Hall by Rm 218 Faucet#1	Initial	2.82	4-3-16	
023	7090616003	5-18-19	2nd Fl Hall by Rm 218 Faucet#2	Initial	4.7	5-29-19	RETURN TO USE
024	16-3290	4-1-16	"	Flushed	2.19	4-4-16	
025	7090616004	5-18-19	2nd Fl Hall by Rm 218 Sink #3	Initial	3.7	5-29-19	RETURN TO USE
026	16-3292	4-1-16	"	Flushed	1.32	4-4-16	
027	16-3293	4-1-16	Teacher's Lounge sink	Initial	8.0	4-3-16	RETURN TO USE
028	16-3294	4-1-16	"	Flushed	6.34	4-4-16	
030	16-3295	4-1-16	Kitchen 2nd Fl. Faucet 1	Initial	5.15	4-3-16	
029	16-3296	4-1-16	"	Flushed	LT 1.00	4-3-16	
031	16-3297	4-1-16		Initial	2.64	4-4-16	
01	16-14982	10-29-16		Initial	2.06	3-3-17	
02	16-14983	10-29-16		Initial	4.85	3-3-17	
04	16-14985	10-29-16		Initial	3.57	3-3-17	
05	16-14986	10-29-16		Initial	2.6	3-3-17	
06	16-14987	10-29-16		Initial	6.24	3-3-17	
07	16-14988	10-29-16		Initial	2.24	3-3-17	
08	16-14989	10-29-16		Initial	8.3	3-3-17	
09	7071629006		Kitchen Hand Sink Faucet	Initial	12.7	11-27-18	RETURN TO USE
11	7090616005		Faucet- Staff Kitchen Bathroom	Initial	3.3	5-29-19	RETURN TO USE
12	16-14993	10-29-16		Initial	13.2	3-3-17	
13	16-14994	10-29-16		Initial	8.34	3-3-17	
14	7090616006		Faucet-Men's Staff by Lounge 1st Fl.	Initial	4.3	5-29-19	RETURN TO USE
15	7071629009		Faucet-Girl's BR- 1st Fl. Rm 112	Initial	5.9	11-27-18	RETURN TO USE
16	16-14997	10-29-16		Initial	1.99	3-3-17	
17	16-14998	10-29-16		Initial	1.96	3-3-17	
18	16-14999	10-29-16		Initial	8.58	3-3-17	
19	16-15000	10-29-16		Initial	2.31	3-3-17	
20	16-15001	10-29-16		Initial	3.58	3-3-17	

Yonkers Public Schools - Potable Water Outlets Sampling, Test Results and Action

Method of Analysis EPA Method 200.8 Rev. 5.4

BOE ID#	Lab ID #	Date of Collection	Sample Description	Initial / Flushed	Lead Concentration ug/L (LT 1.0 = Less Than 1.0)	Date of Analysis	ACTION TAKEN
21	16-15002	10-29-16		Initial	14.4	3-3-17	

OUTLETS TESTED	36
OUTLETS ACTIONABLE	0
REMOVED FROM POTABLE INVENTORY*	3
REMEDIATION/REPLACEMENT PENDING	0

* Fixtures Removed from Potable Inventory; LOCKED and POSTED "Do Not Drink"

019	16-3285	4-1-16	2nd Fl Hall by Rm 214 Faucet	Initial	30.1	4-3-16	ELIMINATED
03	16-14984	10-29-16	Slop sink faucet across from Rm 214	Initial	157.0	3-3-17	LOCKED/POSTED
10	16-14991	10-29-16	Hose Bib at rear of Bldg.	Initial	69.5	3-3-17	LOCKED/POSTED
22	16-15003	10-29-16	Slop Sink Boiler Rm	Initial	20.3	3-22-17	LOCKED/POSTED